

BOQ FOR EXTERIOR PAINTING AND ROAD REPAIRING WORK AT						
HAMREN COLONY						
Sl.No	Description of items	Unit	Qty	Rate(Rs.)	Amount(Rs.)	
1	Repair of road : P.C.C(1:3:6) work of 3" thickness at road after clearing existing P.C.C work ,aggregate,foreign material and cleaning the surface after compacting the surface manually and providing brick soiling.	cum	80			
2	Providing & applying Weather Coat Exterior emulsion paint of approved quality, make & shade, after scrapping the surface with wire brush and applying putty to make the surface smooth ,then applying (minimum) 2 or more coats of paint over acoat of water primer as directed by Bank. Make APEX or equivalent	sqm	3000			
	A) Type D sqm					210 x2 = 420
	B) Type C Sqm					165 x 2 = 330
	C) Type B Sqm					160x6 = 960
	D) Type A Sqm					200x1 = 200
	E) Guard Qr Sqm					165x1 = 165
	F) Branch Building					925 Sqm

The estimated cost is exclusive of statutory taxes (GST)